

Daily report at HG for RC-2 on Oct.23

#	PO #	Item No.	Factory ID HaoGuo : 15326				Product Status 生产状况						Remark
			Item Description	Supplier Ship Date	Supplier Cancel Date	Total Eaches	ctnrs qty	Cutting 裁皮	Drilling 木板打孔	Nailing 枪钉软件	Assembling 装配	Packing 包装	
13	4894636393	RC-2	Mesh Manager's Chair	10/23/2010	10/30/2010	768	2	100%	100%	80%	50%	20%	
14	4896634399	RC-2	Mesh Manager's Chair	10/23/2010	10/30/2010	384	1	100%	100%	50%	10%	5%	
15	4892636276	RC-2	Mesh Manager's Chair	10/23/2010	10/30/2010	768	2	100%	100%	100%	100%	90%	
16	4895634667	RC-2	Mesh Manager's Chair	10/23/2010	10/30/2010	384	1	100%	100%				
3	4892636273	RC-2	Mesh Manager's Chair	10/30/2010	11/06/2010	1536	4						
21	4894636395	RC-2	Mesh Manager's Chair	11/06/2010	11/13/2010	768	2						
22	4896634401	RC-2	Mesh Manager's Chair	11/06/2010	11/13/2010	384	1						
23	4892636278	RC-2	Mesh Manager's Chair	11/06/2010	11/13/2010	768	2						



We checking the color of Star Base,acceptable.



We did the base testing and it was passed.



We are checking the back frame and did the testing, it was passed.





Our QC and factory QC are checking mechanism one by one.





We are checking the back cap of RC-2, acceptable.



test on cap part of back , it is meet our requirement result is pass.




The factory worker are making the arm cushion of RC-2.



The factory worker are Assembling the arm.



Cleaning and packing the arm of RC-2,Right.



Our QC checking arms one by one, The quality of arms meet our request.acceptable.



The factory worker are making the seat cushion of RC-2.



The factory worker are cleaning the seat cushion.right.



Our QC and factory QC checking the seat cushion one by one.



The seat cushion view, acceptable.



Wrinkle, need to repair.



It was damaged, rejected.



Packing the seat cushion, right.

